


RELEASE NOTE

ISOStart+

Demo program for FEIG RFID readers



Note

© Copyright by
FEIG ELECTRONIC GmbH
Industriestraße 1a
D-35781 Weilburg (Germany)
Tel.: +49 6471 3109-0
<http://www.feig.de>
identification-support@feig.de

This manual supercedes all previous editions.
The information contained in this manual is subject to change without notice.

Copying of this document and giving it to others and the use or communication of the contents thereof, are forbidden without express authority. Offenders are liable to the payment of damages. All rights are reserved in the event of the grant of a patent or the registration of a utility model or design.

The information contained in this manual has been gathered with all due care and to the best of our knowledge. FEIG ELECTRONIC GmbH assumes no liability for the accuracy and completeness of the data in this manual. In particular, FEIG ELECTRONIC GmbH cannot be held liable for consequential damages resulting from inaccurate or incomplete information. Since even with our best efforts this document may still contain mistakes, please contact us should you find any errors.

V11.07.00 (2023-05-02)

Changes	Support for the new Reader ID PAD74 (PAD-Antenna with integrated ID CPR74) Updated support for Reader ID LR5400		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.03 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.05 FedmlscCoreApiVC110.dll V5.06.05 FedmlscServiceVC110.dll V8.14.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B ID LR5400
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR30pro ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR70.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.06.00 (2023-02-20)

Changes	Support for the new Reader ID CPR70 Updated support for Reader ID LR5400-A		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.03 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.05 FedmlscCoreApiVC110.dll V5.06.05 FedmlscServiceVC110.dll V8.14.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B ID LR5400-A
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR30pro ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR70.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.05.00 (2022-11-25)

Changes	Updated support for Reader ID LR5400-A Fixes in French USB Keycode Table Updated command set for ID CPR74, ID CPR30pro, ID LR1002		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.03 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.05 FedmlscCoreApiVC110.dll V5.06.05 FedmlscServiceVC110.dll V8.12.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B ID LR5400-A
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR30pro ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.04.00 (2022-09-26)

Changes	Support for new Reader ID LR5400-A Support for new Reader ID CPR30pro		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.03 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.04 FedmlscCoreApiVC110.dll V5.06.04 FedmlscServiceVC110.dll V8.11.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.LR5400-A
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR30pro ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.03.01 (2022-05-12)

Changes	Improvements for ID ECCO Smart HF family		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.03 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.03 FedmlscCoreApiVC110.dll V5.06.03 FedmlscServiceVC110.dll V8.10.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.03.00 (2022-04-08)

Changes	Support for new extensions in ID ECCO Smart HF-BLE firmware v01.03.00 Support for new extensions in ID HyWEAR compact firmware v02.02.00 Improved support for ID CPR30+. New version 08.10.00 of firmware update tool. Support of more STM ST25DV/TV transponders. Some Bugfixes		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.03 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.03 FedmlscCoreApiVC110.dll V5.06.03 FedmlscServiceVC110.dll V8.10.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.02.00 (2021-12-01)

Changes	Support for new ID CPR30+ (replacement for CPR30.xx) – both readers have the same Reader Type! New version of firmware update tool. Some Bugfixes		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.02 FETCP.DLL V3.01.00 FEISC.DLL V7.09.01 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.06.01 FedmlscCoreApiVC110.dll V5.06.01 FedmlscServiceVC110.dll V8.09.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx / CPR30+ ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.01.00 (2021-04-01)

Changes	Support for new ID ECCO Smart 2D-HF-BLE Updated XML configuration files for some Readers Some Bugfixes		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.02 FETCP.DLL V3.01.00 FEISC.DLL V7.09.00 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.05.06 FedmlscCoreApiVC110.dll V5.05.06 FedmlscServiceVC110.dll V8.08.02 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ECCO Smart 2D-HF-BLE ID ISC.M02 ID ISC.M02.M8	ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V11.00.00 (2020-12-16)

Changes	Merge of CPRStart and ISOStart to ISOStart+ Integration of FirmwareUpdateTool Support for new HyWEAR compact sR Support for new Firmware 2.0 for HyWEAR family Discontinued support for Firmware < 2.0 of HyWEAR family LRU500i-PoE/BD: QuickStart Wizard improved, many command dialogs improved Updated XML configuration files for some Readers		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.02 FETCP.DLL V3.01.00 FEISC.DLL V7.09.00 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.05.05 FedmlscCoreApiVC110.dll V5.05.05 FedmlscServiceVC110.dll V8.08.01 ToolkitPro1860vc110.dll libeay32.dll	
Supported ISO 15693 HF Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x	ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x	ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B
Supported ISO 14443 HF Readers	D CPR.02 ID CPR.M02 ID CPR30.xx ID CPR.40xx	ID CPR.40xx-U ID CPR44.xx ID CPR46.xx ID CPR47.xx	ID CPR50.xx ID CPR60.xx ID CPR74 ID MAX50.xx
Supported UHF Readers	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002	ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact sR ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V10.09.02 (2020-08-10)

Changes	Support for new ECCO Smart HF-BLE Updated XML configuration files for some Readers ID MRU102: support for Multiplexer commands		
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.02 FETCP.DLL V3.01.00 FEISC.DLL V7.08.00 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlscCoreVC110.dll V5.05.02 FedmlscCoreApiVC110.dll V5.05.02 FedmlscServiceVC110.dll V8.07.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported Readers	ID ECCO+ ID ECCO Smart HF-BLE ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact xT	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'		

V10.09.00 (2020-05-11)

Changes	Support for new HyWEAR compact xT Support for new ID SPAD.U Updated XML configuration file for some Readers. PRH101-x: Bugfix for command [0xB0][0x22] Lock Multiple Blocks LRU3x00: <ul style="list-style-type: none"> - command [0xAE] Reader Authent added - missing key types added for command [0xAD] Write Reader Authent Keys 	
Dependencies	FECOM.DLL V3.04.01 FEUSB.DLL V6.00.00 FETCP.DLL V3.01.00 FEISC.DLL V7.07.00 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00	FedmlScCoreVC110.dll V5.05.00 FedmlScCoreApiVC110.dll V5.05.00 FedmlScServiceVC110.dll V8.06.00 ToolkitPro1860vc110.dll libeay32.dll
Supported Readers	ID ECCO+ ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID SPAD.U ID HyWEAR compact ID HyWEAR compact xT
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	

V10.08.00 (2020-01-13)

Changes	<p>HyWEAR compact</p> <ul style="list-style-type: none"> - new command [0x8A] Rf On/Off added - new command [0x5F] Set Firmware Upgrade added <p>ID ISC.MRU102</p> <ul style="list-style-type: none"> - Command [0xA3] Write AES Reader Keys modified. <p>ID LRU500i family: Reader Type information displayed in [0x66] Reader Info corrected.</p> <p>Bugfix for tag commands [0x23] Read Multiple Blocks and [0x24] Write Multiple Blocks: block number limitation to 127 after changing the bank back to User memory removed.</p>	
Dependencies	<p>FECOM.DLL V3.04.01</p> <p>FEUSB.DLL V6.00.00</p> <p>FETCP.DLL V3.01.00</p> <p>FEISC.DLL V7.06.00</p> <p>FETCL.DLL V2.04.00</p> <p>FEFU.DLL V2.02.00</p>	<p>FedmlscCoreVC110.dll V5.04.01</p> <p>FedmlscCoreApiVC110.dll V5.04.01</p> <p>FedmlscServiceVC110.dll V8.05.02</p> <p>ToolkitPro1860vc110.dll</p> <p>libeay32.dll</p>
Supported Readers	<p>ID ECCO+</p> <p>ID ISC.M02</p> <p>ID ISC.M02.M8</p> <p>ID ISC.PR101-x</p> <p>ID ISC.MR101-x</p> <p>ID ISC.MR102-x</p> <p>ID ISC.PRH101-x</p> <p>ID ISC.PRH102-x</p> <p>ID ISC.PRH200</p> <p>ID ISC.LR1002</p> <p>ID ISC.LR2500-A</p> <p>ID ISC.LR2500-B</p>	<p>ID ISC.MU02</p> <p>ID ISC.MRU102</p> <p>ID LRU500i-BD</p> <p>ID LRU500i-PoE</p> <p>ID ISC.LRU1002</p> <p>ID ISC.LRU3000</p> <p>ID ISC.PRHD102</p> <p>ID MAX.U1002</p> <p>ID MAX.U500i</p> <p>ID ANT.U500/270-GA</p> <p>ID ANT.U500/270-DM</p> <p>ID HyWEAR compact</p>
File Types	<p>Reader-Editor: XML</p> <p>Protocol-Editor: 'PRT-03'</p>	

V10.07.00 (2019-11-15)

New Features	<p>Updated Configuration for some Readers.</p> <p>Support for ID ISC.MR101/PR101 repaired.</p> <p>ID ISC.MRU102: Command [0xA3] Write AES Reader Keys added.</p> <p>EPC C1G2 Kill and Lock dialogs: all EPCs in ComboBox selectable.</p> <p>ID ISC.PRH102: USB Key-Code Table added.</p> <p>ID LRU500i/MAX.U500i: Selection Masks added.</p> <p>Quick Start Wizard: Detect improved for UART.</p> <p>Prepared for new Windows 10 WHQL certified USB Kernel Driver v3.26</p> <p>Some bugfixes.</p>	
Dependencies	<p>FECOM.DLL V3.04.01</p> <p>FEUSB.DLL V6.00.00</p> <p>FETCP.DLL V3.01.00</p> <p>FEISC.DLL V7.06.00</p> <p>FETCL.DLL V2.04.00</p> <p>FEFU.DLL V2.02.00</p>	<p>FedmlscCoreVC110.dll V5.04.00</p> <p>FedmlscCoreApiVC110.dll V5.04.00</p> <p>FedmlscServiceVC110.dll V8.04.01</p> <p>ToolkitPro1860vc110.dll</p> <p>libeay32.dll</p>
Supported Readers	<p>ID ECCO+</p> <p>ID ISC.M02</p> <p>ID ISC.M02.M8</p> <p>ID ISC.PR101-x</p> <p>ID ISC.MR101-x</p> <p>ID ISC.MR102-x</p> <p>ID ISC.PRH101-x</p> <p>ID ISC.PRH102-x</p> <p>ID ISC.PRH200</p> <p>ID ISC.LR1002</p> <p>ID ISC.LR2500-A</p> <p>ID ISC.LR2500-B</p>	<p>ID ISC.MU02</p> <p>ID ISC.MRU102</p> <p>ID LRU500i-BD</p> <p>ID LRU500i-PoE</p> <p>ID ISC.LRU1002</p> <p>ID ISC.LRU3000</p> <p>ID ISC.PRHD102</p> <p>ID MAX.U1002</p> <p>ID MAX.U500i</p> <p>ID ANT.U500/270-GA</p> <p>ID ANT.U500/270-DM</p> <p>ID HyWEAR compact</p>
File Types	<p>Reader-Editor: XML</p> <p>Protocol-Editor: 'PRT-03'</p>	

V10.06.00 (2019-09-03)

Dependencies	FECOM.DLL V3.04.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEISC.DLL V7.06.00 FETCL.DLL V2.04.00 FEFU.DLL V2.02.00 FedmlscCoreVC110.dll V5.03.00 FedmlscCoreApiVC110.dll V5.03.00 FedmlscServiceVC110.dll V8.04.01 ToolkitPro1860vc110.dll libeay32.dll	
Supported Readers	ID ECCO+ ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID LRU500i-BD ID LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID HyWEAR compact
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes Updated Configuration for some Readers. Support for new Reader ID ECCO+ ID ISC.MU02: support for region Japan added ID LRU500i-PoE: support for UCODE DNA added ID HyWEAR compact: Editor for HID Key Table added	

V10.05.00 (2019-06-14)

Dependencies	FECOM.DLL V3.04.00 FEISC.DLL V7.06.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEFU.DLL V2.02.00 FETCL.DLL V2.04.00 FedmlscCoreVC110.dll V5.03.00 FedmlscCoreApiVC110.dll V5.03.00 FedmlscServiceVC110.dll V8.03.00 ToolkitPro1860vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x ID ISC.PRH102-x ID ISC.PRH200 ID ISC.LR1002 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.LRU500i-PoE ID ISC.LRU1002 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID HyWEAR compact
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes Updated Configuration for some Readers. End of support for the following Readers: ID ISC.MR200, ID ISC.LR200, ID ISC.LR2000, ID ISC.MRU200, ID ISC.LRU1000, ID ISC.LRU2000 End of support for the following Transponder chips: IDS SL900A, IDS SL13A, KSW, Maxim MAX66000 series,	

V10.04.00 (2019-03-18)

Dependencies	FECOM.DLL V3.04.00 FEISC.DLL V7.06.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEFU.DLL V2.02.00 FETCL.DLL V2.04.00 FedmlscCoreVC110.dll V5.02.00 FedmlscCoreApiVC110.dll V5.02.00 FedmlscServiceVC110.dll V8.01.02 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.PRH200 ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU500i-PoE ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID HyWEAR compact
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes Full support for new Scanner ID HyWEAR compact Updated Configuration for some Readers.	

V10.03.06 (2019-02-12)

Dependencies	FECOM.DLL V3.04.00 FEISC.DLL V7.06.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEFU.DLL V2.02.00 FETCL.DLL V2.04.00 FedmlscCoreVC110.dll V5.01.03 FedmlscCoreApiVC110.dll V5.01.03 FedmlscServiceVC110.dll V8.01.01 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.PRH200 ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU500i-PoE ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM ID HyWEAR compact
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes First support for new Scanner ID HyWEAR compact Updated Configuration for some Readers.	

V10.03.04 (2018-12-17)

Dependencies	FECOM.DLL V3.04.00 FEISC.DLL V7.05.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEFU.DLL V2.02.00 FETCL.DLL V2.04.00 FedmlscCoreVC110.dll V5.01.02 FedmlscCoreApiVC110.dll V5.01.02 FedmlscServiceVC110.dll V8.01.00 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.PRH200 ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU500i-PoE ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID MAX.U1002 ID MAX.U500i ID ANT.U500/270-GA ID ANT.U500/270-DM
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes First support for new Reader ID ISC.LRU500i-PoE and ID MAX.U500i Updated Configuration for some Readers.	

V10.03.02 (2018-09-14)

Dependencies	FECOM.DLL V3.04.00 FEISC.DLL V7.05.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEFU.DLL V2.02.00 FETCL.DLL V2.04.00 FedmlscCoreVC110.dll V5.01.01 FedmlscCoreApiVC110.dll V5.01.01 FedmlscServiceVC110.dll V8.00.02 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002 ID ANT.U500/270-GA ID ANT.U500/270-DM
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes For ID ISC.PRH101-U and ID ISC.MR102: new ISO 15693-3 commands Updated Configuration for some Readers.	

V10.03.00 (2018-08-03)

Dependencies	FECOM.DLL V3.04.00 FEISC.DLL V7.05.00 FEUSB.DLL V5.01.00 FETCP.DLL V3.01.00 FEFU.DLL V2.02.00 FETCL.DLL V2.04.00 FedmlscCoreVC110.dll V5.00.00 FedmlscCoreApiVC110.dll V5.00.00 FedmlscServiceVC110.dll V8.00.02 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002 ID ANT.U500/270-GA ID ANT.U500/270-DM
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Some bugfixes Updated Configuration for some Readers.	

V10.02.00 (2018-04-11)

Dependencies	FECOM.DLL V3.03.00 FEISC.DLL V7.04.02 FEUSB.DLL V5.00.00 FETCP.DLL V3.00.00 FEFU.DLL V2.02.00 FETCL.DLL V2.03.02 FedmlscCoreVC110.dll V4.09.03 FedmlscCoreApiVC110.dll V4.09.03 FedmlscServiceVC110.dll V8.00.00 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002 ID ANT.U500/270-GA ID ANT.U500/270-DM
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Functions Authenticate and Challenge for EPC Class1 Gen2 and ISO/IEC 15693-3 Amd4 standard are extended. Updated Configuration for some Readers.	

V10.01.00 (2017-11-16)

Dependencies	FECOM.DLL V3.03.00 FEISC.DLL V7.04.02 FEUSB.DLL V5.00.00 FETCP.DLL V3.00.00 FEFU.DLL V2.01.00 FETCL.DLL V2.03.02 FedmlscCoreVC110.dll V4.09.00 FedmlscCoreApiVC110.dll V4.09.00 FedmlscServiceVC110.dll V8.00.00 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000 ID ISC.LR2500-A ID ISC.LR2500-B	ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002 ID ANT.U500/270-GA ID ANT.U500/270-DM
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers <ul style="list-style-type: none"> Support for new Reader types: ID ANT.U500/270-GA and ID ANT.U500/270-DM 	

V10.00.00 (2017-10-20)

Dependencies	FECOM.DLL V3.03.00 FEISC.DLL V7.04.02 FEUSB.DLL V5.00.00 FETCP.DLL V3.00.00 FEFU.DLL V2.01.00 FETCL.DLL V2.03.02 FedmlscCoreVC110.dll V4.09.00 FedmlscCoreApiVC110.dll V4.09.00 FedmlscServiceVC110.dll V7.09.01 ToolkitPro1730vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers <ul style="list-style-type: none"> • Support for NXP UCODE DNA • Support for NXP ICODE DNA • Support for NXP ICODE SLIX2 • Support for STM ST25DV04K and STM ST25DV16/64K • New communication methods Select, Untraceable, Authenticate, Challenge and ReadBuffer accoding EPC Class1 Gen2 standard v2.0.1 and ISO/IEC 29167-x. • New communication methods Authenticate, Challenge and ReadBuffer accoding ISO/IEC 15693-3 Amd4 and ISO/IEC 29167-x. 	

V9.09.06 (2016-09-27)

Dependencies	FECOM.DLL V3.03.00 FEISC.DLL V7.04.01 FEUSB.DLL V4.02.07 FETCP.DLL V3.00.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.02 FedmlscCoreVC110.dll V4.07.00 FedmlscCoreApiVC110.dll V4.07.00 FedmlscServiceVC110.dll V7.07.00 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Support for improved ID ISC.LRU1002	

V9.09.00 (2015-05-07)

Dependencies	FECOM.DLL V3.02.04 FEISC.DLL V7.03.00 FEUSB.DLL V4.02.06 FETCP.DLL V3.00.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.01 FedmlscCoreVC110.dll V4.06.11 FedmlscCoreApiVC110.dll V4.06.11 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200 ID MAX.U1002
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Many minor improvements Support for new UHF Custom Commands for NXP UCODE DNA with ID ISC.LRU1002 Support for new Reader type ID MAX.U1002	

V9.08.05 (2015-03-04)

Dependencies	FECOM.DLL V3.02.04 FEISC.DLL V7.03.00 FEUSB.DLL V4.02.06 FETCP.DLL V3.00.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.01 FedmlscCoreVC110.dll V4.06.11 FedmlscCoreApiVC110.dll V4.06.11 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Many minor improvements Support for new UHF Custom Commands for EM 4325	

V9.08.02 (2014-10-17)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.03.00 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.01 FedmlscCoreVC110.dll V4.06.08 FedmlscCoreApiVC110.dll V4.06.08 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Support of new feature Seek-Table for ID ISC.PRH200 Many minor improvements and bugfixes	

V9.08.00 (2014-09-12)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.03.00 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.01 FedmlscCoreVC110.dll V4.06.05 FedmlscCoreApiVC110.dll V4.06.05 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Support for new feature Action-on-EPC for ID ISC.LRU3x00 and ID ISC.LRU1002	

V9.07.01 (2014-03-11)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.02.02 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.01 FedmlscCoreVC110.dll V4.06.01 FedmlscCoreApiVC110.dll V4.06.01 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Updates for ID ISC.PRH200 Updates for ID ISC.LRU1002	

V9.07.00 (2013-12-02)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.02.01 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.00 FedmlscCoreVC110.dll V4.05.05 FedmlscCoreApiVC110.dll V4.05.05 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU1002 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102 ID ISC.PRH200
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers New Reader ID ISC.PRH200 New Reader ID ISC.LRU1002	

V9.06.03 (2013-10-31)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.02.01 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.00 FedmlscCoreVC110.dll V4.05.05 FedmlscCoreApiVC110.dll V4.05.05 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Bugfix for Notification-Mode fixes crash after press of Apply-Button	

V9.06.01 (2013-09-02)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.02.01 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.00 FedmlscCoreVC110.dll V4.05.03 FedmlscCoreApiVC110.dll V4.05.03 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Bugfix in XML-Configuration File for LRU3000	

V9.06.00 (2013-07-22)

Dependencies	FECOM.DLL V3.02.03 FEISC.DLL V7.02.00 FEUSB.DLL V4.02.06 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.02.00 FedmlscCoreVC110.dll V4.05.03 ToolkitPro1620vc110.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Bugfix for crash after Detect-Wizard	

V9.05.01 (2013-01-18)

Dependencies	FECOM.DLL V3.02.02 FEISC.DLL V7.01.06 FEUSB.DLL V4.02.05 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.01.01 FedmlscCoreVC100.dll V4.04.01 ToolkitPro1502vc100.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Minor bugfixes Improved Setup for Vista / 7 / 8	

V9.05.00 (2012-12-12)

Dependencies	FECOM.DLL V3.02.02 FEISC.DLL V7.01.06 FEUSB.DLL V4.02.04 FETCP.DLL V2.02.00 FEFU.DLL V2.00.00 FETCL.DLL V2.01.01 FedmlscCoreVC100.dll V4.04.00 ToolkitPro1502vc100.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Minor bugfixes Development changed to VS 2010 Ready for Windows 8	

V9.04.00 (2012-08-21)

Dependencies	FECOM.DLL V3.02.01 FEISC.DLL V7.01.04 FEUSB.DLL V4.02.02 FETCP.DLL V2.01.01 FEFU.DLL V2.00.00 FETCL.DLL V2.01.01 FedmlscCoreVC80.dll V4.03.00 ToolkitPro1502vc80.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Updated Configuration for some Readers Minor bugfixes	

V9.01.02 (2012-03-29)

Dependencies	FECOM.DLL V3.01.01 FEISC.DLL V7.01.00 FEUSB.DLL V4.01.00 FETCP.DLL V2.01.01 FEFU.DLL V2.00.00 FETCL.DLL V2.01.00 FedmlscCoreVC80.dll V4.01.00 ToolkitPro1502vc80.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR1002 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Support for new Reader: ID ISC.LR1002 Updated QuickStartWizard for ID ISC.MRU102 Updated Configuration for ID ISC.MRU102 Logging into a file of BRM and NTF data	

V9.01.00 (30.11.2011)

Dependencies	FECOM.DLL V3.00.00 FEISC.DLL V7.00.01 FEUSB.DLL V4.00.01 FETCP.DLL V2.00.00 FEFU.DLL V2.00.00 FETCL.DLL V2.00.00 FedmlscCoreVC80.dll V4.00.05 ToolkitPro1502vc80.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Modified Detect-Dialog USB Keycode table for ID ISC.MU02 (requires firmware version 1.3.128 or higher)	

V9.00.00 (27.07.2011)

Dependencies	FECOM.DLL V3.00.00 FEISC.DLL V7.00.00 FEUSB.DLL V4.00.00 FETCP.DLL V2.00.00 FEFU.DLL V2.00.00 FETCL.DLL V2.00.00 FedmlscCoreVC80.dll V4.00.00 ToolkitPro1502vc80.dll libeay32.dll	
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000	ID ISC.LR2500-A ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC	
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'	
New Features	Support for new Reader: ID ISC.LR2500-A Support for UIDs up to 96 Bytes Support for LRU3000 with Firmware >= V2.0.0 Support for LRU3000 with Firmware < V2.0.0 discontinued	

V8.03.02 (19.04.2011)

Dependencies	FECOM.DLL V2.08.12 FEISC.DLL V6.03.00 FEUSB.DLL V3.06.01 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.07 FedmlscCoreVC80.dll V3.03.01 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU102 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	Support for new Reader: ID ISC.MRU102-x Support for ISO 15693 Transponders with more than 256 data blocks

V8.03.01 (14.02.2011)

Dependencies	FECOM.DLL V2.08.12 FEISC.DLL V6.02.01 FEUSB.DLL V3.06.01 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.06 FedmlscCoreVC80.dll V3.03.00 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.MR102-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	Support for new Reader: ID ISC.MR102-x

V8.03.00 (26.01.2011)

Dependencies	FECOM.DLL V2.08.12 FEISC.DLL V6.02.01 FEUSB.DLL V3.06.01 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.06 FedmlscCoreVC80.dll V3.03.00 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LR2500-B ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	- Support for new Reader: ID ISC.LR2500-B

V8.02.03 (21.06.2010)

Dependencies	FECOM.DLL V2.08.12 FEISC.DLL V6.01.00 FEUSB.DLL V3.05.00 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.06 FedmlscCoreVC80.dll V3.02.00 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
Supported external Devices	ID ISC.ANT1690/600-GPC ID ISC.ANT1700/740-GPC
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	- Support for People Counter in HF-Gates

V8.02.02 (26.4.2010)

Dependencies	FECOM.DLL V2.08.11 FEISC.DLL V6.00.03 FEUSB.DLL V3.05.00 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.06 FedmlscCoreVC80.dll V3.01.05 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	- New NXP UHF Custom Commands

V8.02.01 (18.3.2010)

Dependencies	FECOM.DLL V2.08.11 FEISC.DLL V6.00.02 FEUSB.DLL V3.05.00 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.05 FedmlscCoreVC80.dll V3.01.02 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	- USB-Keycode-Table for MRU200

V8.02.00 (19.2.2010)

Dependencies	FECOM.DLL V2.08.11 FEISC.DLL V6.00.00 FEUSB.DLL V3.05.00 FETCP.DLL V1.02.05 FEFU.DLL V1.03.00 FETCL.DLL V1.00.05 FedmlscCoreVC80.dll V3.01.00 ToolkitPro1310vc80.dll libeay32.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	<ul style="list-style-type: none">- QuickStartWizard for all Reader types- Support for encyphered protocol transmission with LRU3000

V8.01.06 (15.12.2009)

Dependencies	FECOM.DLL V2.08.09 FEISC.DLL V5.07.17 FEUSB.DLL V3.05.00 FETCP.DLL V1.02.04 FEFU.DLL V1.03.00 FETCL.DLL V1.00.04 FedmlscCoreVC80.dll V3.00.18 ToolkitPro1310vc80.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.LRU3000 ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	<ul style="list-style-type: none">- Support for new Reader: ID ISC.LRU3000- Ready for Windows 7- Many new ISO 15693 Custom Commands- SDK Manuals in Help-Menu- Technical Support Request Forms in Help-Menu

V8.01.00 (22.06.2009)

Dependencies	FECOM.DLL V2.08.09 FEISC.DLL V5.07.11 FEUSB.DLL V3.03.06 FETCP.DLL V1.02.04 FEFU.DLL V1.03.00 FETCL.DLL V1.00.03 FedmlscCoreVC80.dll V3.00.08 ToolkitPro1211vc80.dll
Supported Readers	ID ISC.M02 ID ISC.M02.M8 ID ISC.PR101-x ID ISC.MR101-x ID ISC.PRH101-x / ID ISC.PRH102-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MU02 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	<ul style="list-style-type: none">- first release with support for all Readers- QuickStartWizard- Support for extended Reader Working-Modes with multiple Antennas (if supported by Reader)

V8.00.08 (18.11.2008) – Edition for ID ISC.PRHD102

Dependencies	FECOM.DLL V2.08.03 FEISC.DLL V5.07.05 FEUSB.DLL V3.03.05 FETCP.DLL V1.02.04 FEFU.DLL V1.02.00 FedmlscCoreVC80.dll V3.00.00 ToolkitPro1120vc80.dll
Supported Readers	ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	Group EPCglobal added Command Group: <i>[0xA0] Reader Login</i> added

V8.00.05 (04.09.2008) – Edition for ID ISC.PRHD102

Dependencies	FECOM.DLL V2.08.03 FEISC.DLL V5.07.02 FEUSB.DLL V3.03.05 FETCP.DLL V1.02.04 FEFU.DLL V1.03.00 FedmlscCoreVC80.dll V3.00.00 ToolkitPro1120vc80.dll
Supported Readers	ID ISC.PRHD102
File Types	Reader-Editor: XML Protocol-Editor: 'PRT-03'
New Features	Redesign of ISOStart First Release

V7.05.01 (15.11.2007)

Dependencies	FECOM.DLL V2.08.00 FEISC.DLL V5.05.08 FEUSB.DLL V3.03.01 FETCP.DLL V1.02.03 FEFU.DLL V1.02.00 XT2000LIB.DLL
Supported Readers	ID ISC.M01 ID ISC.M02 ID ISC.PR100-x / ID ISC.PR101-x ID ISC.MR100-x / ID ISC.MR101-x ID ISC.PRH100-x / ID ISC.PRH101-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.MRU200 ID ISC.LRU1000 ID ISC.LRU2000 ID CPR.02 ID CPR.M02 ID CPR.M02-U ID CPR.04 ID CPR.04-USB
File Types	Reader-Editor: Version 'ISC-02' and XML Protocol-Editor: Version 'PRT-02' and 'PRT-03'
New Features	Support for new Reader ID ISC.MRU200

V7.03.00 (18.01.2007)

Dependencies	FECOM.DLL V2.08.00 FEISC.DLL V5.05.00 FEUSB.DLL V2.05.00 FETCP.DLL V1.02.03 FEFU.DLL V1.02.00 XT2000LIB.DLL
Supported Readers	ID ISC.M01 ID ISC.M02 ID ISC.PR100-x / ID ISC.PR101-x ID ISC.MR100-x / ID ISC.MR101-x ID ISC.PRH100-x / ID ISC.PRH101-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LRU1000 ID ISC.LRU2000 ID CPR.02 ID CPR.M02 ID CPR.M02-U ID CPR.04 ID CPR.04-USB
File Types	Reader-Editor: Version 'ISC-02' and XML Protocol-Editor: Version 'PRT-02' and 'PRT-03'
New Features	Support of new Features for ID CPR-Family, ID ISC.MR200, ID ISC.LR2000 and ID ISC.LRU2000

V7.02.00 (09.10.2006)

Dependencies	FECOM.DLL V2.07.00 FEISC.DLL V5.04.11 FEUSB.DLL V2.03.02 FETCP.DLL V1.02.03 FEFU.DLL V1.02.00 XT2000LIB.DLL
Supported Readers	ID ISC.M01 ID ISC.M02 ID ISC.PR100-x / ID ISC.PR101-x ID ISC.MR100-x / ID ISC.MR101-x ID ISC.PRH100-x / ID ISC.PRH101-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LRU1000 ID ISC.LRU2000 ID CPR.02 ID CPR.M02 ID CPR.M02-U ID CPR.04 ID CPR.04-USB
File Types	Reader-Editor: Version 'ISC-02' and XML Protocol-Editor: Version 'PRT-02' and 'PRT-03'
New Features	Support of new Features for ID CPR-Family, ID ISC.MR200, ID ISC.LR2000 and ID ISC.LRU2000

V7.01.00 (21.07.2006)

Dependencies	FECOM.DLL V2.07.00 FEISC.DLL V5.04.05 FEUSB.DLL V2.03.02 FETCP.DLL V1.02.03 FEFU.DLL V1.02.00 XT2000LIB.DLL
Supported Readers	ID ISC.M01 ID ISC.M02 ID ISC.PR100-x / ID ISC.PR101-x ID ISC.MR100-x / ID ISC.MR101-x ID ISC.PRH100-x / ID ISC.PRH101-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LRU1000 ID ISC.LRU2000 ID CPR.02 ID CPR.M02 ID CPR.M02-U ID CPR.04 ID CPR.04-USB
File Types	Reader-Editor: Version 'ISC-02' and XML Protocol-Editor: Version 'PRT-02' and 'PRT-03'
New Features	Support for new Reader: <ul style="list-style-type: none">• ID ISC.LRU2000 Support of new Features for ID ISC.MR200 and ID ISC.LR2000

V7.00.00 (22.05.2006)

Dependencies	FECOM.DLL V2.07.00 FEISC.DLL V5.04.02 FEUSB.DLL V2.03.02 FETCP.DLL V1.02.03 FEFU.DLL V1.02.00 XT2000LIB.DLL
Supported Readers	ID ISC.M01 ID ISC.M02 ID ISC.PR100-x / ID ISC.PR101-x ID ISC.MR100-x / ID ISC.MR101-x ID ISC.PRH100-x / ID ISC.PRH101-x ID ISC.MR200 ID ISC.LR200 ID ISC.LR2000 ID ISC.LRU1000 ID CPR.02 ID CPR.M02 ID CPR.M02-U ID CPR.04 ID CPR.04-USB
File Types	Reader-Editor: Version 'ISC-02' and XML Protocol-Editor: Version 'PRT-02' and 'PRT-03'
New Features	Support of new Reader Mode (Notification Mode) for ID ISC.LRU1000 and ID ISC.LR2000